

Oil Filter Contact with A/C Compressor Hose

Year	Make and Model	Engine
2012-2013	Chevrolet Captiva Sport	3.0L (RPO LFW)

Condition/Concern

Oil leak from the oil filter due to filter rubbing on the A/C compressor hose.

Recommendation/Instructions

- If this condition is encountered, call GM's Technical Assistance Center to start a case (800-222-1020).
- Reference GM TSB 15-NA-055 and 15-00-90-001.
- In the meantime dealers are encouraged to replace the PG2500 oil filter with the shorter PG2222 to gain clearance.



Premium Guard - PG2500



Premium Guard - PG2222

Customer Information

- Please communicate to the customer that an alternate oil filter has been installed to increase the clearance between the oil filter and the A/C line and that this oil filter should be used during future oil and filter changes

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
J0950	Oil Filter Replacement	Use published labor operation time