

GM OIL FILTER PG5839 / PG5839EX INSTALLATION PROCEDURE

2017 - 2018 COLORADO/CANYON - 3.6L

These filters will require attention when being installed in a 2017/2018 Colorado/Canyon equipped with 3.6L. There is a potential service problem that may happen when performing an oil change on these vehicles. During the replacement of the oil filter, please be aware that the oil filter insert (center tube) is still in it's original position in the oil filter adapter/housing. This insert could become detached from the adapter and lodged inside the filter, causing it to be thrown away by accident.

Housing **Missing** Insert



Housing **With** Insert



If the insert is missing, then critical engine failure can occur.

Reference GM TSB #PIP5560A

Do you have a question? Comment? Please let us know how we can help you.
Contact us at pgfilters@pgfilters.com.